



**Gray**

Map Lot 024-312-021-000

Account 3918

Location 17 HAYDEN LN

Card 1


Of 1

8/05/2024

Building Style	<b>7 Contemporary</b>		
1.Conv.	5.Garrison	9.NE farm	
2.Ranch	6.Split	10.Colonia	
3.R Ranch/	7.Contemp	11.Cottage	
4.Cape	8.Log	12.Gambrel	
Dwelling Units	<b>1</b>		
Other Units	<b>0</b>		
Stories	<b>2 Two Story</b>		
1.1	4.1.5	7.	
2.2	5.1.75	8.	
3.3	6.2.5	9.	
Exterior Walls	<b>2 Vinyl/Aluminum</b>		
1.Clapboar	5.Stucco	9.B & B	
2.Vin/Al	6.Brick	10.Cemplan	
3.Compos./	7.Stone	11.Concret	
4.Asbestos	8.Wood Shi	12.Wood Bo	
Roof Surface	<b>1 Asphalt Shingles</b>		
1.Asphalt	4.Composit	7.Other	
2.Slate	5.Wood	8.	
3.Metal	6.Roll Roo	9.	
SF Masonry Trim	<b>0</b>		
SOLAR VOLTAIC	<b>0</b>		
OPEN-4-	<b>0</b>		
Year Built	<b>1980</b>		
Year Remodeled	<b>2004</b>		
Foundation	<b>1 Concrete</b>		
1.Concrete	4.Wood	7.	
2.C Block	5.Slab	8.	
3.Br/Stone	6.Piers	9.	
Basement	<b>5 Crawl Space</b>		
1.1/4 Bmt	4.Full Bmt	7.	
2.1/2 Bmt	5.Crwl	8.	
3.3/4 Bmt	6.	9.None	
Bsmt Gar # Cars	<b>0</b>		
Wet Basement	<b>9 No Basement</b>		
1.Dry	4.	7.	
2.Damp	5.	8.	
3.Wet	6.	9.	

SF Bsmt Living	<b>0</b>		
Fin Bsmt Grade	<b>0 0</b>		
Secondary Heat	<b>0</b>		
Heat Type	<b>100%</b>	<b>1 Hot Water BB</b>	
1.HWBB	5.FWA	9.None	
2.HWCI	6.Monitor	10.UNH2F	
3.HWRF	7.Electric	11.Geother	
4.Steam	8.F/Wall	12.Heat/Co	
Cool Type	<b>0%</b>	<b>9 None</b>	
1.Central	4.W&C Air	7.	
2.Evapor	5.	8.	
3.H Pump	6.	9.None	
Kitchen Style	<b>2 Typical</b>		
1.Modern	4.Obsolete	7.	
2.Typical	5.	8.	
3.Old Type	6.	9.None	
Bath(s) Style	<b>2 Typical Bath(s)</b>		
1.Modern	4.Obsolete	7.	
2.Typical	5.	8.	
3.Old Type	6.	9.None	
# Rooms	<b>6</b>		
# Bedrooms	<b>3</b>		
# Full Baths	<b>3</b>		
# Half Baths	<b>0</b>		
# Addn Fixtures	<b>0</b>		
# Fireplaces	<b>1</b>		

Layout	<b>1 Typical</b>		
1.Typical	4.	7.	
2.Inadeq	5.	8.	
3.	6.	9.	
Attic	<b>9 None</b>		
1.1/4 Fin	4.Full Fin	7.	
2.1/2 Fin	5.F/Stair	8.	
3.3/4 Fin	6.	9.None	
Insulation	<b>1 Full</b>		
1.Full	4.Minimal	7.	
2.Heavy	5.	8.	
3.Capped	6.	9.None	
Unfinished %	<b>0%</b>		
Grade & Factor	<b>4 Good 110%</b>		
1.E Grade	4.B Grade	7.SC Grade	
2.C Grade	5.A Grade	8.	
3.Grade	6.AA Grade	9.Same	
SQFT (Footprint)	<b>692</b>		
Condition	<b>7 Very Good</b>		
1.Poor	4.Avg	7.V G	
2.Fair	5.Avg	8.Exc	
3.Avg-	6.Good	9.Same	
Phys. % Good	<b>0%</b>		
Funct. % Good	<b>95%</b>		
Functional Code	<b>9 None</b>		
1.Incomp	4.Delap	7.Delay	
2.O-Built	5.Bsmt	8.Long term	
3.Damage	6.Style	9.None	
Econ. % Good	<b>100%</b>		
Economic Code	<b>None</b>		
0.None	3.No Power	6.Obsolete	
1.Location	4.Generate	9.None	
2.Encroach	5.Flood Pl	9.	
Entrance Code	<b>1 Interior Inspect</b>		
1.Interior	4.Vacant	7.	
2.Refusal	5.Estimate	8.	
3.Informed	6.	9.	
Information Code	<b>1 Owner</b>		
1.Owner	4.Agent	7.	
2.Relative	5.Estimate	8.	
3.Tenant	6.Other	9.	



Date Inspected 8/04/2015

**Additions, Outbuildings & Improvements**

Type	Year	Units	Grade	Cond	Phys.	Funct.	Sound Value
1 One Story Frame	0	468	0 0	0	0	100 %	
68 Wood Deck	0	379	0 0	0	0	100 %	
22 Encl Frame Porch	0	220	0 0	0	0	100 %	
1 One Story Frame	0	140	0 0	0	0	100 %	
4 1 & 1/2 Story Fr	0	84	0 0	0	0	100 %	
24 Frame Shed	0	80	3 100	4	0	100 %	
21 Open Frame	0	24	0 0	0	0	100 %	
64 Tennis Court	0	7200	4 100	4	0	100 %	
68 Wood Deck	0	50	0 0	0	0	100 %	

- 1.One Story Fram
- 2.Two Story Fram
- 3.Three Story Fr
- 4.1 & 1/2 Story
- 5.1 & 3/4 Story
- 6.2 & 1/2 Story
- 21.Open Frame Por
- 22.Encl Frame Por
- 23.Frame Garage
- 24.Frame Shed
- 25.Frame Bay Wind
- 26.1SFr Overhang
- 27.Unfin Basement
- 28.Unfinished Att
- 29.Finished Attic

