

Gray

Map Lot 042-013-008-000

Account 514

Location 26 HEMLOCK LN

Card 1

Of 1


8/05/2024

| | | |
|--|--|--------------------------------------|
| Building Style 3 Raised Ranch/Split | SF Bsmt Living 852 | Layout 1 Typical |
| 1.Conv. 5.Garrison 9.NE farm | Fin Bsmt Grade 3 110 | 1.Typical 4. 7. |
| 2.Ranch 6.Split 10.Colonia | Secondary Heat 2 | 2.Inadeq 5. 8. |
| 3.R Ranch/ 7.Contemp 11.Cottage | Heat Type 100% 1 Hot Water BB | 3. 6. 9. |
| 4.Cape 8.Log 12.Gambrel | 1.HWBB 5.FWA 9.None | Attic 9 None |
| Dwelling Units 1 | 2.HWCI 6.Monitor 10.UNH2F | 1.1/4 Fin 4.Full Fin 7. |
| Other Units 0 | 3.HWRF 7.Electric 11.Geother | 2.1/2 Fin 5.FI/Stair 8. |
| Stories 1 One Story | 4.Steam 8.FI/Wall 12.Heat/Co | 3.3/4 Fin 6. 9.None |
| 1.1 4.1.5 7. | Cool Type 0% 9 None | Insulation 1 Full |
| 2.2 5.1.75 8. | 1.Central 4.W&C Air 7. | 1.Full 4.Minimal 7. |
| 3.3 6.2.5 9. | 2.Evapor 5. 8. | 2.Heavy 5. 8. |
| Exterior Walls 12 Wood boards | 3.H Pump 6. 9.None | 3.Capped 6. 9.None |
| 1.Clapboar 5.Stucco 9.B & B | Kitchen Style 2 Typical | Unfinished % 0% |
| 2.Vin/Al 6.Brick 10.Cemplan | 1.Modern 4.Obsolete | Grade & Factor 3 Average 110% |
| 3.Compos./ 7.Stone 11.Concret | 2.Typical 5. 8. | 1.E Grade 4.B Grade 7.SC Grade |
| 4.Asbestos 8.Wood Shi 12.Wood Bo | 3.Old Type 6. 9.None | 2.C Grade 5.A Grade 8. |
| Roof Surface 1 Asphalt Shingles | Bath(s) Style 2 Typical Bath(s) | 3.D Grade 6.AA Grade 9.Same |
| 1.Asphalt 4.Composit 7.Other | 1.Modern 4.Obsolete 7. | SQFT (Footprint) 900 |
| 2.Slate 5.Wood 8. | 2.Typical 5. 8. | Condition 4 Average |
| 3.Metal 6.Roll Roo 9. | 3.Old Type 6. 9.None | 1.Poor 2.Avg 7.V G |
| SF Masonry Trim 0 | # Rooms 8 | 2.Fair 3.Good 8.Exc |
| SOLAR VOLTAIC 0 | # Bedrooms 4 | 3.Avg- 9.Same |
| OPEN-4- 0 | # Full Baths 2 | Phys. % Good 0% |
| Year Built 1975 | # Half Baths 1 | Funct. % Good 100% |
| Year Remodeled 0 | # Addn Fixtures 1 | Functional Code 9 None |
| Foundation 1 Concrete | # Fireplaces 0 | 1.Incomp 4.Delap 5.Layoff |
| 1.Concrete 4.Wood 7. | | 2.O-Built 5.Bsmt 6.Long term |
| 2.C Block 5.Slab 8. | | 3.Damage 6.Style 7.None |
| 3.Br/Stone 6.Piers 9. | | Econ. % Good 100% |
| Basement 4 Full Basement | | Economic Code None |
| 1.1/4 Bmt 4.Full Bmt 7. | | 0.None 3.No Power 6.Obsolete |
| 2.1/2 Bmt 5.CrwI 8. | | 1.Location 4.Generate 9.None |
| 3.3/4 Bmt 6. 9.None | | 2.Encroach 5.Flood Pl 9. |
| Bsmt Gar # Cars 0 | | Entrance Code 5 Estimated |
| Wet Basement 1 Dry Basement | | 1.Interior 4.Vacant 7. |
| 1.Dry 4. 7. | | 2.Refusal 5.Estimate 8. |
| 2.Damp 5. 8. | | 3.Informed 6. 9. |
| 3.Wet 6. 9. | | Information Code 5 Estimate |
| | | 1.Owner 4.Agent 7. |
| | | 2.Relative 5.Estimate 8. |
| | | 3.Tenant 6.Other 9. |

Date Inspected 5/24/2024

Additions, Outbuildings & Improvements

| Type | Year | Units | Grade | Cond | Phys. | Funct. | Sound Value |
|-------------------|------|-------|-------|------|-------|--------|-------------------|
| 79 1/2 St/Garage | 0 | 552 | 0 0 | 0 | 0 % | 100 % | |
| 1 One Story Frame | 1995 | 300 | 0 0 | 0 | 0 % | 100 % | 1.One Story Fram |
| 24 Frame Shed | 0 | 144 | 2 100 | 4 | 0 % | 100 % | 2.Two Story Fram |
| 63 Swimming Pool | 1995 | 612 | 3 100 | 4 | 0 % | 100 % | 3.Three Story Fr |
| 61 Canopy | 0 | 144 | 2 100 | 4 | 0 % | 100 % | 4.1 & 1/2 Story |
| 24 Frame Shed | 2012 | 192 | 3 100 | 4 | 0 % | 100 % | 5.1 & 3/4 Story |
| 68 Wood Deck | 2018 | 80 | 3 100 | 4 | 0 % | 100 % | 6.2 & 1/2 Story |
| 68 Wood Deck | 2012 | 144 | 4 100 | 4 | 0 % | 100 % | 21.Open Frame Por |
| 23 Frame Garage | 0 | 552 | 3 100 | 4 | 0 % | 100 % | 22.Encl Frame Por |
| | | | | | | | 23.Frame Garage |
| | | | | | | | 24.Frame Shed |
| | | | | | | | 25.Frame Bay Wind |
| | | | | | | | 26.1SFr Overhang |
| | | | | | | | 27.Unfin Basement |
| | | | | | | | 28.Unfinished Att |
| | | | | | | | 29.Finished Attic |



Proposed Value

