



**Gray**

Map Lot 035-025-011-000

Account 1372

Location 46 SHAKER RD

Card 1

Of 2


8/05/2024

|                                      |   |                                      |
|--------------------------------------|---|--------------------------------------|
| Building Style <b>4 Cape Cod</b>     | SF Bsmt Living <b>0</b>                 | Layout <b>1 Typical</b>              |
| 1.Conv. 5.Garrison 9.NE farm         | Fin Bsmt Grade <b>0 0</b>               | 1.Typical 4. 7.                      |
| 2.Ranch 6.Split 10.Colonia           | Secondary Heat <b>0</b>                 | 2.Inadeq 5. 8.                       |
| 3.R Ranch/ 7.Contemp 11.Cottage      | Heat Type <b>100% 5 Forced Warm Air</b> | 3. 6. 9.                             |
| 4.Cape 8.Log 12.Gambrel              | 1.HWBB 5.FWA 9.None                     | Attic <b>9 None</b>                  |
| Dwelling Units <b>1</b>              | 2.HWCI 6.Monitor 10.UNH2F               | 1.1/4 Fin 4.Full Fin 7.              |
| Other Units <b>0</b>                 | 3.HWRF 7.Electric 11.Geother            | 2.1/2 Fin 5.FI/Stair 8.              |
| Stories <b>5 One &amp; 3/4 Story</b> | 4.Steam 8.FI/Wall 12.Heat/Co            | 3.3/4 Fin 6. 9.None                  |
| 1.1 4.1.5 7.                         | Cool Type <b>0% 9 None</b>              | Insulation <b>1 Full</b>             |
| 2.2 5.1.75 8.                        | 1.Central 4.W&C Air 7.                  | 1.Full 4.Minimal 7.                  |
| 3.3 6.2.5 9.                         | 2.Evapor 5. 8.                          | 2.Heavy 5. 8.                        |
| Exterior Walls <b>1 Clapboard</b>    | 3.H Pump 6. 9.None                      | 3.Capped 6. 9.None                   |
| 1.Clapboar 5.Stucco 9.B & B          | Kitchen Style <b>2 Typical</b>          | Unfinished % <b>0%</b>               |
| 2.Vin/Al 6.Brick 10.Cemplan          | 1.Modern 4.Obsolete                     | Grade & Factor <b>3 Average 110%</b> |
| 3.Compos./ 7.Stone 11.Concret        | 2.Typical 5. 8.                         | 1.E Grade 4.B Grade 7.SC Grade       |
| 4.Asbestos 8.Wood Shi 12.Wood Bo     | 3.Old Type 6. 9.None                    | 2.O Grade 5.A Grade 8.               |
| Roof Surface <b>3 Metal</b>          | Bath(s) Style <b>2 Typical Bath(s)</b>  | 3.O Grade 6.AA Grade 9.Same          |
| 1.Asphalt 4.Composit 7.Other         | 1.Modern 4.Obsolete 7.                  | SQFT (Footprint) <b>936</b>          |
| 2.Slate 5.Wood 8.                    | 2.Typical 5. 8.                         | Condition <b>4 Average</b>           |
| 3.Metal 6.Roll Roo 9.                | 3.Old Type 6. 9.None                    | 1.Poor 4.Avg 7.V G                   |
| SF Masonry Trim <b>0</b>             | # Rooms <b>5</b>                        | 2.Fair 5.Avg 8.Exc                   |
| SOLAR VOLTAIC <b>0</b>               | # Bedrooms <b>3</b>                     | 3.Avg- 6.Good 9.Same                 |
| OPEN-4- <b>0</b>                     | # Full Baths <b>1</b>                   | Phys. % Good <b>0%</b>               |
| Year Built <b>1972</b>               | # Half Baths <b>1</b>                   | Funct. % Good <b>100%</b>            |
| Year Remodeled <b>0</b>              | # Addn Fixtures <b>0</b>                | Functional Code <b>9 None</b>        |
| Foundation <b>1 Concrete</b>         | # Fireplaces <b>1</b>                   | 1.Incomp 4.Delap 5.Delay             |
| 1.Concrete 4.Wood 7.                 |   | 2.O-Built 5.Bsmt 8.Long term         |
| 2.C Block 5.Slab 8.                  |   | 3.Damage 6.Style 9.None              |
| 3.Br/Stone 6.Piers 9.                |   | Econ. % Good <b>100%</b>             |
| Basement <b>4 Full Basement</b>      |   | Economic Code <b>None</b>            |
| 1.1/4 Bmt 4.Full Bmt 7.              |   | 0.None 3.No Power 6.Obsolete         |
| 2.1/2 Bmt 5.Crwl 8.                  |   | 1.Location 4.Generate 9.None         |
| 3.3/4 Bmt 6. 9.None                  |   | 2.Encroach 5.Flood Pl 9.             |
| Bsmt Gar # Cars <b>0</b>             |   | Entrance Code <b>5 Estimated</b>     |
| Wet Basement <b>1 Dry Basement</b>   |   | 1.Interior 4.Vacant 7.               |
| 1.Dry 4. 7.                          |   | 2.Refusal 5.Estimate 8.              |
| 2.Damp 5. 8.                         |   | 3.Informed 6. 9.                     |
| 3.Wet 6. 9.                          |   | Information Code <b>5 Estimate</b>   |
|                                      |   | 1.Owner 4.Agent 7.                   |
|                                      |   | 2.Relative 5.Estimate 8.             |
|                                      |   | 3.Tenant 6.Other 9.                  |

Date Inspected 5/17/2024

**Additions, Outbuildings & Improvements**

| Type              | Year | Units | Grade | Cond | Phys. | Funct. | Sound Value |
|-------------------|------|-------|-------|------|-------|--------|-------------|
| 1 One Story Frame | 0    | 238   | 0 0   | 0    | 0     | 100 %  |             |
| 21 Open Frame     | 0    | 68    | 0 0   | 0    | 0     | 100 %  |             |
| 73 1.25 St Garage | 0    | 624   | 0 0   | 0    | 0     | 100 %  |             |
| 1 One Story Frame | 0    | 264   | 0 0   | 0    | 0     | 100 %  |             |
| 60 Pole Barn      | 1986 | 640   | 2 100 | 4    | 0     | 100 %  |             |
| 57 1.5 St Barn    | 1977 | 1500  | 2 100 | 4    | 0     | 100 %  |             |
| 60 Pole Barn      | 1991 | 960   | 2 100 | 4    | 0     | 100 %  |             |
| 24 Frame Shed     | 1977 | 550   | 2 100 | 4    | 0     | 100 %  |             |
| 61 Canopy         | 0    | 550   | 3 100 | 4    | 0     | 100 %  |             |
| 24 Frame Shed     | 1980 | 240   | 2 100 | 4    | 0     | 100 %  |             |



Proposed Value



